



6 DEALER MANUAL FOR M820 (MM G532.250.C)



CONTENT

6.1 Introduction	. 2
6.2 Specifications	3
6.2.1 Outline and Geometric Size	.3
6.2.2 Surface	4
6.2.3 Storage Information	4
6.3 Drive Unit Installation	5
6.3.1 List of Tools to be Used	5

6.4 Maintena	ince
6.3.7 Exterr	nal Speed Sensor Installation
6.3.6 Crank	Installation
6.3.5 Chain	Wheel Installation
6.3.4 Drive	Unit Cover Installation
6.3.3 Moto	r Installation
6.3.2 Cablir	ng5

6.1 INTRODUCTION




Product Model
MM G532.250.C

• Scope

Applies only to electrically powered bicycles, and specifically designed or licensed for Pedelec. It is suitable for road bikes on city roads, cement and asphalt roads and travel bikes on gravel roads. It should not be used commercial purposes.

• Identification

The following graphic, is the identification numbers of the product, which are shown on the housing:




Note: Content in the label is important information about this product. Please do not remove the information from the motor.


6.2 SPECIFICATIONS


Motor model: MM G532.250.C

Rated power (W)	250
Rated voltage (V)	43
Waterproof	IP65
Certification	EMC / ISO13849
Outdoor Temperatures	-20 °C~45 °C

6.2.1 Outline and Geometric Size







6.2.2 Surface

Shockproof black coating

6.2.3 Storage Information


The pedelec should be stored in a ventilated dry room. Avoid storing the pedelec near strong magnetic objects.

6.3 DRIVE UNIT INSTALLATION

6.3.1 List of Tools to be Used

Use of the Tools	Tools
To tighten/loosen bolts onto the frame interface and the drive unit	Internal hex wrench
To tighten/loosen nuts onto the frame interface and the drive unit	Socket spanner
To tighten/loosen M15 waterproof screws on the crank	Internal hex wrench
To tighten/loosen lock-nut on chain wheel	BAFANG Tool
To tighten/loosen screws on the speed sensor	Cross screwdriver
	Star screwdriver

6.3.2 Cabling




a Male 8 pin connector from EB-BUS to speed sensor
B Male 8 pin connector at the drive unit
b Female 8 pin connector from EB-BUS

A Female 8 pin connector at the drive unit

- C Male connector for power supply at the drive unit
- Female connector for power supply at the battery


6.3.3 Motor Installation



1) Align the three mounting holes of the drive unit with the mounting holes in the bike frame. From the right of the bike frame insert three M8 bolts into the mounting holes in the bike frame and the drive unit.

2) From the left, use standard tool tighten the three M8 Lock nuts with flat washer on the bike frame. Tightening torque requirement: 35 N.m.


6.3.4 Drive Unit Cover Installation






Use a screwdriver (T10) and with three M3*8 star pan head screws to fasten the motor cover and the interface together, the tightening torque requirement is 0.9-1.0 N.m.

6.3.5 Chain Wheel Installation




Put the chain wheel onto the spline shaft of the drive unit. Use BAFANG's tool to fasten the lock ring counterclockwise onto the spline shaft. Torque requirement: 35 N.m.



6.3.6 Crank Installation

Mount right crank on the right shaft, with internal hex wrench fasten the M15 screws on the shaft (tightening torque is 45-50 N.m). Same way will left crank mount on the shaft (Note: Please guarantee the left and right crank parallel).

6.3.7 External Speed Sensor Installation



Fasten the mounting screws through the speed sensor and with a cross screwdriver. Tightening the speed sensor onto the frame. Torque requirement: 1.5-2 N.m. (Note: Please make sure the gap between the speed sensor and the magnetic unit is between 10 and 20 mm.)

Now place the magnet on the spoke of the wheel ensuring it is aligned to the middle of the speed sensor. And with a star key tighten the magnet in place. Torque requirement: 1.5-2 N.m.

6.4 MAINTENANCE

- Maintenance must be carried out by authorized personnel with the correct equipment.
- Do not disassemble the motor.
- Do not use thinners or other solvents to clean the components. Such substances can damage the surfaces.
- Avoid water submerging, to keep the components protected.
- Avoid using high-pressure cleaning jets.
- For prolonged storage, turn off the battery and avoid storing near heat sources.



